

**Flood Control Project Maintenance  
Levee Inspections**

**2015 Channel Summary Report**

**Overall Unit and Item Ratings**

## San Joaquin County Flood Control and Water Conservation District

---

### Duck Creek Diversion Channel

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

### North Littlejohn Creek

Overall Unit Rating	Rated Item	Item Rating
<b>M</b>	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

### South Littlejohn Creek

Overall Unit Rating	Rated Item	Item Rating
<b>M</b>	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	M
	Revetments & Other Structural Appurtenances	A
	Encroachments	M

### South Littlejohn Creek North Branch

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	M
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

**Flood Control Project Maintenance****Unit Cover Sheet****2015 Channel Inspection Results****San Joaquin County Flood Control and Water Conservation District**

Channel
Duck Creek Diversion Channel

Channel Rating	<b>A</b>
Date of Inspection	07/13/2015
DWR Inspector	Pavel Kazi
Accompanied By	Jay Jauregui SJCFC&WCD
	Jim Caruso SJCFC&WCD

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
Duck Creek Diversion Channel	0.90	07/13/2015 07/13/2015	Pavel Kazi

Check Point / View

**Diversion Structure / Down**

Rating **	A	Issue No.	31	GPS Lat/Long
Issue Type +	Ma	Location *		37.938270 °
Category	Rivers, Channels & Designated Flood			-120.990130 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_43_c _ 2012_31			

Action/Comments

Inspector Comments: Minimal vegetation in the channel should not impede the flow.

Photo 1 of 2 : CH\_2015\_NA0017\_43\_31\_20150817\_00014.jpg



View of the vegetation in the diversion channel looking downstream during 2015 inspection.

Rating **	A	Issue No.	31 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.938270 °
Category	Rivers, Channels & Designated Flood			-120.990130 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_43_c _ 2012_31			

Photo 2 of 2 : CH\_2015\_NA0017\_43\_31\_20150710\_00012.jpg



View of the vegetation in the diversion channel looking downstream during 2014 inspection.

Rating **	A	Issue No.	1	GPS Lat/Long
Issue Type +	Ma	Location *		37.938270 °
Category	Rivers, Channels & Designated Flood			-120.990130 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_43_c _ 2012_1			

Action/Comments

Inspector Comments: No sedimentation was present at this site.

No Photos

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
Duck Creek Diversion Channel	0.90	07/13/2015 07/13/2015	Pavel Kazi

Check Point / View

**Diversion Structure / Down (cont)**

Rating **	A	Issue No.	32	GPS Lat/Long
Issue Type +	Ma	Location *		37.938270 °
Category	Rivers, Channels & Designated Flood			-120.990130 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_43_c _ 2012_32			
Action/Comments				
Inspector Comments: No erosion or bank caving is present in the channel.				

No Photos

Rating **	N	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		37.938270 °
Category	Rivers, Channels & Designated Flood			-120.990130 °
Item	Revetments			
DWR ID	DWR_NA0017_43_c _ 2012_33			
Action/Comments				
Inspector Comments: No revetment is present at this location.				

No Photos

Rating **	A	Issue No.	34	GPS Lat/Long
Issue Type +	En	Location *		37.938270 °
Category	Rivers, Channels & Designated Flood			-120.990130 °
Item	Encroachments			
DWR ID	DWR_NA0017_43_c _ 2012_34			
Action/Comments				
Inspector Comments: No trash or debris observed in the channel.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
Duck Creek Diversion Channel	0.90	07/13/2015 07/13/2015	Pavel Kazi

Check Point / View

**Farmington Rd/ Hwy 4 / Up**

Rating **	A	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		37.930250 °
Category	Rivers, Channels & Designated Flood			-120.991220 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_43_c _ 2012_11			

Action/Comments

Inspector Comments: The Minimal vegetation in the channel doesn't appear to obstruct the flow of the channel.

Photo 1 of 1 : CH\_2015\_NA0017\_43\_11\_20150817\_00015.jpg



View of the vegetation in the channel looking upstream.

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		37.930250 °
Category	Rivers, Channels & Designated Flood			-120.991220 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_43_c _ 2012_12			

Action/Comments

Inspector Comments: No sedimentation was present during inspection.

No Photos

Rating **	A	Issue No.	13	GPS Lat/Long
Issue Type +	Ma	Location *		37.930250 °
Category	Rivers, Channels & Designated Flood			-120.991220 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_43_c _ 2012_13			

Action/Comments

Inspector Comments: No erosion or bank caving was present during inspection.

No Photos

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
Duck Creek Diversion Channel	0.90	07/13/2015 07/13/2015	Pavel Kazi

Check Point / View

**Farmington Rd/ Hwy 4 / Up (cont)**

Rating **	A	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		37.930250 °
Category	Rivers, Channels & Designated Flood			-120.991220 °
Item	Revetments			
DWR ID	DWR_NA0017_43_c _ 2012_14			
Action/Comments				
Inspector Comments: Existing riprap appears to be properly maintained.				

Photo 1 of 2 : CH\_2015\_NA0017\_43\_14\_20150817\_00017.jpg



View of the revetments on the right bank of the channel looking upstream.

Rating **	A	Issue No.	14 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.930250 °
Category	Rivers, Channels & Designated Flood			-120.991220 °
Item	Revetments			
DWR ID	DWR_NA0017_43_c _ 2012_14			

Photo 2 of 2 : CH\_2015\_NA0017\_43\_14\_20150817\_00016.jpg



View of the revetments on the left bank of the channel looking upstream.

Rating **	A	Issue No.	2	GPS Lat/Long
Issue Type +	Ma	Location *		37.930250 °
Category	Rivers, Channels & Designated Flood			-120.991220 °
Item	Encroachments			
DWR ID	DWR_NA0017_43_c _ 2012_2			
Action/Comments				
Inspector Comments: No trash or debris was found during inspection.				

No Photos

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
Duck Creek Diversion Channel	0.90	07/13/2015 07/13/2015	Pavel Kazi

Check Point / View

**Farmington Rd/ Hwy 4 / Down**

Rating **	A	Issue No.	16	GPS Lat/Long
Issue Type +	Ma	Location *		37.930250 °
Category	Rivers, Channels & Designated Flood			-120.991220 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_43_c _ 2012_16			
Action/Comments				
Inspector Comments: Minimal vegetation is present in the channel but it doesn't appear to obstruct the flow of the channel.				

Photo 1 of 1 : CH\_2015\_NA0017\_43\_16\_20150817\_00018.jpg



View of the vegetation growth looking downstream in the channel.

Rating **	A	Issue No.	17	GPS Lat/Long
Issue Type +	Ma	Location *		37.930250 °
Category	Rivers, Channels & Designated Flood			-120.991220 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_43_c _ 2012_17			
Action/Comments				
Inspector Comments: No sediments are present at this location.				

No Photos

Rating **	A	Issue No.	18	GPS Lat/Long
Issue Type +	Ma	Location *		37.930250 °
Category	Rivers, Channels & Designated Flood			-120.991220 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_43_c _ 2012_18			
Action/Comments				
Inspector Comments: No bank caving or erosion was found in the channel.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
Duck Creek Diversion Channel	0.90	07/13/2015 07/13/2015	Pavel Kazi

Check Point / View				
Farmington Rd/ Hwy 4 / Down (cont)				
Rating **	A	Issue No.	19	GPS Lat/Long
Issue Type +	Ma	Location *		37.929807 °
Category	Rivers, Channels & Designated Flood			-120.991183 °
Item	Revetments			
DWR ID	DWR_NA0017_43_c _ 2012_19			
Action/Comments				
Inspector Comments: Existing riprap appears to be properly maintained.				

Photo 1 of 2 : CH\_2015\_NA0017\_43\_19\_20150817\_00019.jpg



View of the revetments on the left bank of the channel looking downstream.

Rating **	A	Issue No.	<b>19 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.929807 °
Category	Rivers, Channels & Designated Flood			-120.991183 °
Item	Revetments			
DWR ID	DWR_NA0017_43_c _ 2012_19			

Photo 2 of 2 : CH\_2015\_NA0017\_43\_19\_20150817\_00020.jpg



View of the revetments on the right bank of the channel looking downstream.

Rating **	A	Issue No.	20	GPS Lat/Long
Issue Type +	Ma	Location *		37.930250 °
Category	Rivers, Channels & Designated Flood			-120.991220 °
Item	Encroachments			
DWR ID	DWR_NA0017_43_c _ 2012_20			
Action/Comments				
Inspector Comments: No trash or debris are obstructing the flow of the channel.				

No Photos

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
Duck Creek Diversion Channel	0.90	07/13/2015 07/13/2015	Pavel Kazi

Check Point / View

**Confluence with South Littlejohn Creek / Up**

Rating **	A	Issue No.	21	GPS Lat/Long
Issue Type +	Ma	Location *		37.925730 °
Category	Rivers, Channels & Designated Flood			-120.992290 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_43_c_2012_21			

Action/Comments

Inspector Comments: Vegetation growth in the channel doesn't appeared to impede the flow.

Rating **	A	Issue No.	21 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.925730 °
Category	Rivers, Channels & Designated Flood			-120.992290 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_43_c_2012_21			

Rating **	A	Issue No.	21 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.925730 °
Category	Rivers, Channels & Designated Flood			-120.992290 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_43_c_2012_21			

Photo 1 of 4 : CH\_2015\_NA0017\_43\_21\_20150817\_00022.jpg



View of the channel looking upstream during 2015 inspection.

Photo 2 of 4 : CH\_2015\_NA0017\_43\_21\_20150710\_00009.jpg



View of the channel looking upstream during 2014 inspection.

Photo 3 of 4 : CH\_2015\_NA0017\_43\_21\_20150817\_00021.jpg



View of the confluence during 2015 inspection.

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
Duck Creek Diversion Channel	0.90	07/13/2015 07/13/2015	Pavel Kazi

Check Point / View

**Confluence with South Littlejohn Creek / Up (cont)**

Rating **	A	Issue No.	<b>21 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.925730 °
Category	Rivers, Channels & Designated Flood			-120.992290 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_43_c _ 2012_21			

Action/Comments

Inspector Comments: Vegetation growth in the channel doesn't appeared to impede the flow.

Photo 4 of 4 : CH\_2015\_NA0017\_43\_21\_20150710\_00011.jpg



View of the confluence during 2014 inspection.

Rating **	A	Issue No.	<b>22</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.925730 °
Category	Rivers, Channels & Designated Flood			-120.992290 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_43_c _ 2012_22			

Action/Comments

Inspector Comments: No sediment was present at this location.

No Photos

Rating **	A	Issue No.	<b>23</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.925730 °
Category	Rivers, Channels & Designated Flood			-120.992290 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_43_c _ 2012_23			

Action/Comments

Inspector Comments: No erosion was present during inspection.

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
Duck Creek Diversion Channel	0.90	07/13/2015 07/13/2015	Pavel Kazi

Check Point / View				
Confluence with South Littlejohn Creek / Up (cont)				
Rating **	N	Issue No.	24	GPS Lat/Long
Issue Type +	Ma	Location *		37.925730 °
Category	Rivers, Channels & Designated Flood			-120.992290 °
Item	Revetments			
DWR ID	DWR_NA0017_43_c _ 2012_24			
Action/Comments				
Inspector Comments: No revetments were present around the channel.				

No Photos

No Photos

Rating **	A	Issue No.	25	GPS Lat/Long
Issue Type +	Ma	Location *		37.925730 °
Category	Rivers, Channels & Designated Flood			-120.992290 °
Item	Encroachments			
DWR ID	DWR_NA0017_43_c _ 2012_25			
Action/Comments				
Inspector Comments: No trash or debris are obstructing the flow of the channel.				

No Photos

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance****Unit Cover Sheet****2015 Channel Inspection Results****San Joaquin County Flood Control and Water Conservation District**

Channel
North Littlejohn Creek

Channel Rating	<b>M</b>
Date of Inspection	07/13/2015 - 07/17/2015
DWR Inspector	Pavel Kazi
Accompanied By	Jay Jauregui SJCFC&WCD

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Upstream Limit / Up**

Rating **	A	Issue No.	6	GPS Lat/Long
Issue Type +	Ma	Location *		37.919430 °
Category	Rivers, Channels & Designated Flood			-121.034800 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c _ 2012_6			
Action/Comments				
Inspector Comments: No vegetation is obstructing the flow of the channel.				

Photo 1 of 1 : CH\_2015\_NA0017\_42\_6\_20150818\_00044.jpg



View of the vegetation on the upstream of the channel.

Rating **	A	Issue No.	7	GPS Lat/Long
Issue Type +	Ma	Location *		37.919430 °
Category	Rivers, Channels & Designated Flood			-121.034800 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c _ 2012_7			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

Rating **	A	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		37.919430 °
Category	Rivers, Channels & Designated Flood			-121.034800 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c _ 2012_8			
Action/Comments				
Inspector Comments: No erosion is present at this location during inspection.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Upstream Limit / Up (cont)**

Rating **	N	Issue No.	9	GPS Lat/Long
Issue Type +	Ma	Location *		37.919430 °
Category	Rivers, Channels & Designated Flood			-121.034800 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c _ 2012_9			

Action/Comments

Inspector Comments: No revetments are found at this location.

No Photos

Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		37.919430 °
Category	Rivers, Channels & Designated Flood			-121.034800 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c _ 2012_10			

Action/Comments

Inspector Comments: No trash, debris, or obstruction is present at this location.

No Photos

Check Point / View

**Hewit Lane / Up**

Rating **	A	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		37.920600 °
Category	Rivers, Channels & Designated Flood			-121.037920 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c _ 2012_11			

Action/Comments

Inspector Comments: Vegetation will not impede the flow of the channel.

Photo 1 of 2 : CH\_2015\_NA0017\_42\_11\_20150818\_00045.jpg



View of the channel looking upstream during 2015 inspection.

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Hewit Lane / Up (cont)**

Rating **	A	Issue No.	11 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.920600 °
Category	Rivers, Channels & Designated Flood			-121.037920 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c _ 2012_11			
Action/Comments				
Inspector Comments: Vegetation will not impede the flow of the channel.				

Photo 2 of 2 : CH\_2015\_NA0017\_42\_11\_20150710\_00004.jpg



View of vegetation looking upstream during 2014 inspection.

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		37.920584 °
Category	Rivers, Channels & Designated Flood			-121.037914 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c _ 2012_12			
Action/Comments				
Inspector Comments: No sedimentation is present on the channel.				

No Photos

Rating **	N	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		37.920584 °
Category	Rivers, Channels & Designated Flood			-121.037914 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c _ 2012_14			
Action/Comments				
Inspector Comments: Revetments are not present at this location.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Hewit Lane / Up (cont)**

Rating **	A	Issue No.	15	GPS Lat/Long
Issue Type +	Ma	Location *		37.920584 °
Category	Rivers, Channels & Designated Flood			-121.037914 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c _ 2012_15			

Action/Comments

Inspector Comments: No trash or debris are present in the channel.

No Photos

Rating **	A	Issue No.	112	GPS Lat/Long
Issue Type +	Ma	Location *		37.920600 °
Category	Rivers, Channels & Designated Flood			-121.037920 °
Item	Concrete Surfaces			
DWR ID	DWR_NA0017_42_c _ 2012_112			

Action/Comments

Inspector Comments: The concrete surface appeared to be in good condition with no negligible spalling, scalling or cracking.

No Photos

Rating **	M	Issue No.	113	GPS Lat/Long
Issue Type +	Ma	Location *		37.920600 °
Category	Rivers, Channels & Designated Flood			-121.037920 °
Item	Gates			
DWR ID	DWR_NA0017_42_c _ 2012_113			

Action/Comments

Inspector Comments: Slide gates appeared to be in good operational condition, but gate wheels were missing from the gate.

Photo 1 of 1 : CH\_2015\_NA0017\_42\_113\_20150818\_00046.jpg



View of the slide gate looking upstream of the channel.

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Hewit Lane / Down**

Rating **	A	Issue No.	16	GPS Lat/Long
Issue Type +	Ma	Location *		37.920584 °
Category	Rivers, Channels & Designated Flood			-121.037914 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c _ 2012_16			
Action/Comments				
Inspector Comments: Walnut tree exists on left side of the shoulder. It doesn't obstructed the flow, but it could fall down in the creek.				

Photo 1 of 1 : CH\_2015\_NA0017\_42\_16\_20150818\_00047.jpg



View of the channel looking downstream during 2015 inspection.

Rating **	A	Issue No.	17	GPS Lat/Long
Issue Type +	Ma	Location *		37.920584 °
Category	Rivers, Channels & Designated Flood			-121.037914 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c _ 2012_17			
Action/Comments				
Inspector Comments: No sedimentation is present at this location.				

No Photos

Rating **	A	Issue No.	18	GPS Lat/Long
Issue Type +	Ma	Location *		37.920584 °
Category	Rivers, Channels & Designated Flood			-121.037914 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c _ 2012_18			
Action/Comments				
Inspector Comments: No erosion or bank caving is present.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
Hewit Lane / Down (cont)				
Rating **	N	Issue No.	19	GPS Lat/Long
Issue Type +	Ma	Location *		37.920584 °
Category	Rivers, Channels & Designated Flood			-121.037914 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c _ 2012_19			
Action/Comments				
Inspector Comments: No revetments are present at this location.				

No Photos

No Photos

Rating **	A	Issue No.	20	GPS Lat/Long
Issue Type +	Ma	Location *		37.920584 °
Category	Rivers, Channels & Designated Flood			-121.037914 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c _ 2012_20			
Action/Comments				
Inspector Comments: No trash or debris are present in the channel.				

No Photos

No Photos

Check Point / View				
Van Allen Rd / Up				
Rating **	M	Issue No.	21	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c _ 2012_21			
Action/Comments				
Inspector Comments: Tree branches on the channel may cause an obstruction in the flow.				

Photo 1 of 1 : CH\_2015\_NA0017\_42\_21\_20150818\_00048.jpg




Photo 1 of 1 : CH\_2015\_NA0017\_42\_21\_20150818\_00048.jpg



View of the vegetation looking upstream of the channel.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
Van Allen Rd / Up (cont)				
Rating **	A	Issue No.	22	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c _ 2012_22			
Action/Comments				
Inspector Comments: No sedimentation was found during inspection.				

No Photos

No Photos

Rating **	A	Issue No.	23	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c _ 2012_23			
Action/Comments				
Inspector Comments: No erosion is present at this location during inspection.				

No Photos

No Photos

Rating **	N	Issue No.	24	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c _ 2012_24			
Action/Comments				
Inspector Comments: No revetments are present at this location.				

No Photos

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
Van Allen Rd / Up (cont)				
Rating **	A	Issue No.	25	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c _ 2012_25			
Action/Comments				
Inspector Comments: No debris were present during inspection.				

No Photos

Check Point / View				
Van Allen Rd / Down				
Rating **	M	Issue No.	26	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c _ 2012_26			
Action/Comments				
Inspector Comments: Various lengths of logs, and vegetation growth appeared to impede the flow of the channel.				

Photo 1 of 1 : CH\_2015\_NA0017\_42\_26\_20150818\_00049.jpg



View of heavy vegetation looking downstream of the channel.

Rating **	A	Issue No.	27	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c _ 2012_27			
Action/Comments				
Inspector Comments: No sedimentation is present at this location.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Van Allen Rd / Down (cont)**

Rating **	A	Issue No.	28	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c _ 2012_28			
Action/Comments				
Inspector Comments: No erosion is present at this location during inspection.				

No Photos

Rating **	N	Issue No.	29	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c _ 2012_29			
Action/Comments				
Inspector Comments: No revetments are present at this location.				

No Photos

Rating **	A	Issue No.	30	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c _ 2012_30			
Action/Comments				
Inspector Comments: A broken pipe was found on the bank of the channel during inspection.				

Photo 1 of 1 : CH\_2015\_NA0017\_42\_30\_20150818\_00050.jpg



View of the broken pipe on the downstream of the channel.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Jack Tone Rd / Up**

Rating **	M	Issue No.	31	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460 °
Category	Rivers, Channels & Designated Flood			-121.147570 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_31			
Action/Comments				
Inspector Comments: Minimal vegetation exists on the channel.				

Rating **	M	Issue No.	<b>31 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460 °
Category	Rivers, Channels & Designated Flood			-121.147570 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_31			

Photo 1 of 2 : CH\_2015\_NA0017\_42\_31\_20150818\_00051.jpg



View of the channel looking upstream during 2015 inspection.

Photo 2 of 2 : CH\_2015\_NA0017\_42\_31\_20150710\_00011.jpg



View of upstream of the channel during 2014 inspection.

Rating **	A	Issue No.	32	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460 °
Category	Rivers, Channels & Designated Flood			-121.147570 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_32			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present on the channel.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
Jack Tone Rd / Up (cont)				
Rating **	A	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460 °
Category	Rivers, Channels & Designated Flood			-121.147570 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c _ 2012_33			
Action/Comments				
Inspector Comments: No erosion is present at this location during inspection.				

No Photos

No Photos

Rating **	N	Issue No.	34	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460 °
Category	Rivers, Channels & Designated Flood			-121.147570 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c _ 2012_34			
Action/Comments				
Inspector Comments: No revetments are present at this location.				

No Photos

No Photos

Rating **	A	Issue No.	35	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460 °
Category	Rivers, Channels & Designated Flood			-121.147570 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c _ 2012_35			
Action/Comments				
Inspector Comments: No trash was present on the channel during inspection.				

No Photos

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Jack Tone Rd / Down**

Rating **	A	Issue No.	36	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460
Category	Rivers, Channels & Designated Flood			-121.147570
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c _ 2012_36			
Action/Comments				
Inspector Comments: Minimal vegetation on the channel should not obstruct the flow.				

Photo 1 of 1 : CH\_2015\_NA0017\_42\_36\_20150818\_00052.jpg



View of the channel looking downstream.

Rating **	A	Issue No.	37	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460
Category	Rivers, Channels & Designated Flood			-121.147570
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c _ 2012_37			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

Rating **	A	Issue No.	38	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460
Category	Rivers, Channels & Designated Flood			-121.147570
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c _ 2012_38			
Action/Comments				
Inspector Comments: No erosion is present at this location during inspection.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Jack Tone Rd / Down (cont)**

Rating **	N	Issue No.	39	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460 °
Category	Rivers, Channels & Designated Flood			-121.147570 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c _ 2012_39			

Action/Comments

Inspector Comments: No revetments are present at this location.

No Photos

Rating **	A	Issue No.	40	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460 °
Category	Rivers, Channels & Designated Flood			-121.147570 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c _ 2012_40			

Action/Comments

Inspector Comments: No trash or debris is present at this location.

No Photos

Check Point / View

**Mariposa Rd / Up**

Rating **	A	Issue No.	41	GPS Lat/Long
Issue Type +	Ma	Location *		37.915600 °
Category	Rivers, Channels & Designated Flood			-121.189270 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c _ 2012_41			

Action/Comments

Inspector Comments: Minimal vegetation on the channel should not impede the flow.

Photo 1 of 2 : CH\_2015\_NA0017\_42\_41\_20150818\_00053.jpg



View of upstream of the channel during 2015 inspection.

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Mariposa Rd / Up (cont)**

Rating **	A	Issue No.	<b>41 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.915600 °
Category	Rivers, Channels & Designated Flood			-121.189270 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c _ 2012_41			

Action/Comments

Inspector Comments: Minimal vegetation on the channel should not impede the flow.

Photo 2 of 2 : CH\_2015\_NA0017\_42\_41\_20150710\_00015.jpg



View of upstream of the channel during 2014 inspection.

Rating **	A	Issue No.	<b>42</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.915600 °
Category	Rivers, Channels & Designated Flood			-121.189270 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c _ 2012_42			

Action/Comments

Inspector Comments: No sedimentaion is present.

No Photos

Rating **	A	Issue No.	<b>43</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.915600 °
Category	Rivers, Channels & Designated Flood			-121.189270 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c _ 2012_43			

Action/Comments

Inspector Comments: No erosion observed at this location.

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Mariposa Rd / Up (cont)**

Rating **	A	Issue No.	<b>44</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.915600 °
Category	Rivers, Channels & Designated Flood			-121.189270 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c _ 2012_44			

Action/Comments

Inspector Comments: Existing revetments appear to be properly maintained.

No Photos

Rating **	A	Issue No.	<b>45</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.915600 °
Category	Rivers, Channels & Designated Flood			-121.189270 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c _ 2012_45			

Action/Comments

Inspector Comments: No trash or other obstructions are present in the channel.

No Photos

Check Point / View

**Mariposa Rd / Down**

Rating **	M	Issue No.	<b>46</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.915600 °
Category	Rivers, Channels & Designated Flood			-121.189270 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c _ 2012_46			

Action/Comments

Inspector Comments: Vegetation growth may obstruct the flow of the channel.

Photo 1 of 1 : CH\_2015\_NA0017\_42\_46\_20150818\_00054.jpg



View of vegetation on the downstream of the channel.

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

Mariposa Rd / Down (cont)

Rating **	A	Issue No.	47	GPS Lat/Long
Issue Type +	Ma	Location *		37.915600 °
Category	Rivers, Channels & Designated Flood			-121.189270 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c _ 2012_47			
Action/Comments				
Inspector Comments: No sedimentaion is present.				

No Photos

No Photos

Rating **	A	Issue No.	48	GPS Lat/Long
Issue Type +	Ma	Location *		37.915600 °
Category	Rivers, Channels & Designated Flood			-121.189270 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c _ 2012_48			
Action/Comments				
Inspector Comments: No erosion observed at this location.				

No Photos

No Photos

Rating **	N	Issue No.	49	GPS Lat/Long
Issue Type +	Ma	Location *		37.915600 °
Category	Rivers, Channels & Designated Flood			-121.189270 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c _ 2012_49			
Action/Comments				
Inspector Comments: No revetments are present at this location.				

No Photos

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Mariposa Rd / Down (cont)**

Rating **	A	Issue No.	50	GPS Lat/Long
Issue Type +	Ma	Location *		37.915600 °
Category	Rivers, Channels & Designated Flood			-121.189270 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c _ 2012_50			

Action/Comments

Inspector Comments: Trash and debris were present in the channel during inspection, but it may not impede the flow of the channel.

Photo 1 of 1 : CH\_2015\_NA0017\_42\_50\_20150818\_00055.jpg



View of debris in the downstream end of the channel.

Check Point / View

**Highway 99 / Up**

Rating **	A	Issue No.	51	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c _ 2012_51			

Action/Comments

Inspector Comments: Minimal vegetation on the channel will not impede the flow of the channel.

Photo 1 of 2 : CH\_2015\_NA0017\_42\_51\_20150818\_00056.jpg



View of the vegetation on the channel looking upstream during 2015 inspection.

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Highway 99 / Up (cont)**

Rating **	A	Issue No.	<b>51 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c _ 2012_51			

Action/Comments

Inspector Comments: Minimal vegetation on the channel will not impede the flow of the channel.

Photo 2 of 2 : CH\_2015\_NA0017\_42\_51\_20150710\_00019.jpg



View of the vegetation on the channel looking upstream during 2014 inspection.

Rating **	M	Issue No.	<b>52</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c _ 2012_52			

Action/Comments

Inspector Comments: Sedimentation is present at this location.

Photo 1 of 1 : CH\_2015\_NA0017\_42\_52\_20150818\_00057.jpg



View of sedimentation on the upstream of the channel.

Rating **	A	Issue No.	<b>53</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c _ 2012_53			

Action/Comments

Inspector Comments: No erosion was present during inspection.

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
Highway 99 / Up (cont)				
Rating **	N	Issue No.	54	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c _ 2012_54			
Action/Comments				
Inspector Comments: No revetments was found at this location.				

No Photos

Rating **	M	Issue No.	55	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239
Category	Rivers, Channels & Designated Flood			-121.225915
Item	Encroachments			
DWR ID	DWR_NA0017_42_c _ 2012_55			
Action/Comments				
Inspector Comments: Trash, and various debris are obstructing the flow of the channel.				

Photo 1 of 1 : CH\_2015\_NA0017\_42\_55\_20150818\_00058.jpg



View of the encroachments on the upstream of the channel.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Highway 99 / Down**

Rating **	A	Issue No.	<b>56</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c _ 2012_56			

Action/Comments

Inspector Comments: Minimal vegetation does not impede the flow on the channel.

Photo 1 of 1 : CH\_2015\_NA0017\_42\_56\_20150819\_00059.jpg



View of the downstream end of the channel.

Rating **	A	Issue No.	<b>57</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c _ 2012_57			

Action/Comments

Inspector Comments: No sedimentation is present during the inspection.

No Photos

Rating **	A	Issue No.	<b>58</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c _ 2012_58			

Action/Comments

Inspector Comments: No erosion is present.

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Highway 99 / Down (cont)**

Rating **	N	Issue No.	59	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c _ 2012_59			

Action/Comments

Inspector Comments: No revetments are present at this location.

No Photos

Rating **	M	Issue No.	60	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c _ 2012_60			

Action/Comments

Inspector Comments: Few trash is present during the inspection.

No Photos

Check Point / View

**Pock Lane / Up**

Rating **	A	Issue No.	61	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c _ 2012_61			

Action/Comments

Inspector Comments: Minimal vegetation may not impede the flow of the channel.

Photo 1 of 2 : CH\_2015\_NA0017\_42\_61\_20150819\_00060.jpg



View of the channel looking upstream during 2015 inspection.

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Pock Lane / Up (cont)**

Rating **	A	Issue No.	<b>61 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c _ 2012_61			

Action/Comments

Inspector Comments: Minimal vegetation may not impede the flow of the channel.

Photo 2 of 2 : CH\_2015\_NA0017\_42\_61\_20150710\_00024.jpg



View of the channel looking upstream during 2014 inspection.

Rating **	A	Issue No.	<b>62</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c _ 2012_62			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

Rating **	A	Issue No.	<b>63</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c _ 2012_63			

Action/Comments

Inspector Comments: No erosion is present at this location.

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Pock Lane / Up (cont)**

Rating **	N	Issue No.	64	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c _ 2012_64			

Action/Comments

Inspector Comments: No revetments are present at this location.

No Photos

Rating **	A	Issue No.	65	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c _ 2012_65			

Action/Comments

Inspector Comments: No trash or debris is present in the channel.

No Photos

Check Point / View

**Pock Lane / Down**

Rating **	A	Issue No.	66	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c _ 2012_66			

Action/Comments

Inspector Comments: Minimal vegetation may not impede the flow of the channel.

Photo 1 of 1 : CH\_2015\_NA0017\_42\_66\_20150819\_00061.jpg



View of the channel looking downstream.

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
Pock Lane / Down (cont)				
Rating **	A	Issue No.	67	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c _ 2012_67			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

No Photos

Rating **	A	Issue No.	68	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c _ 2012_68			
Action/Comments				
Inspector Comments: No erosion or bank caving is present at this location.				

No Photos

No Photos

Rating **	N	Issue No.	69	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c _ 2012_69			
Action/Comments				
Inspector Comments: No revetments are present at this location.				

No Photos

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
Pock Lane / Down (cont)				
Rating **	A	Issue No.	70	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c _ 2012_70			
Action/Comments				
Inspector Comments: No trash or debris is present in the channel.				

No Photos

Check Point / View				
South B Street / Up				
Rating **	M	Issue No.	71	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c _ 2012_71			
Action/Comments				
Inspector Comments: Minimal vegetation is present in the channel.				

Photo 1 of 1 : CH\_2015\_NA0017\_42\_71\_20150819\_00062.jpg



View of vegetation on the channel looking upstream.

Rating **	A	Issue No.	72	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c _ 2012_72			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
South B Street / Up (cont)				
Rating **	A	Issue No.	73	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c _ 2012_73			
Action/Comments				
Inspector Comments: No erosion is present at this location.				

No Photos

Rating **	N	Issue No.	74	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c _ 2012_74			
Action/Comments				
Inspector Comments: No revetments are present at this location.				

No Photos

Rating **	A	Issue No.	75	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c _ 2012_75			
Action/Comments				
Inspector Comments: No trash was present.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**South B Street / Down**

Rating **	M	Issue No.	<b>76</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_76			

Action/Comments

Inspector Comments: Minimal vegetation on the channel may impede the flow.

Photo 1 of 2 : CH\_2015\_NA0017\_42\_76\_20150819\_00063.jpg



View of the channel looking downstream on 2015 inspection.

Photo 2 of 2 : CH\_2015\_NA0017\_42\_76\_20150710\_00030.jpg



View of the channel looking downstream on 2014 inspection.

Rating **	A	Issue No.	<b>77</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_77			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
South B Street / Down (cont)				
Rating **	A	Issue No.	78	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c _ 2012_78			
Action/Comments				
Inspector Comments: No erosion is present at this location.				

No Photos

No Photos

Rating **	N	Issue No.	79	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c _ 2012_79			
Action/Comments				
Inspector Comments: No revetments are present at this location.				

No Photos

No Photos

Rating **	A	Issue No.	80	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c _ 2012_80			
Action/Comments				
Inspector Comments: No trash or debris was present during the inspection.				

No Photos

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Airport Way / Up**

Rating **	M	Issue No.	<b>81</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c _ 2012_81			

Action/Comments

Inspector Comments: Minimal vegetation may impede the flow of the channel.

Photo 1 of 1 : CH\_2015\_NA0017\_42\_81\_20150819\_00064.jpg



View of the vegetation on the channel looking upstream.

Rating **	A	Issue No.	<b>82</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c _ 2012_82			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

Rating **	A	Issue No.	<b>83</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c _ 2012_83			

Action/Comments

Inspector Comments: No erosion is present at this location.

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Airport Way / Up (cont)**

Rating **	N	Issue No.	<b>84</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c _ 2012_84			

Action/Comments

Inspector Comments: No revetments are present at this location.

No Photos

Rating **	A	Issue No.	<b>85</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c _ 2012_85			

Action/Comments

Inspector Comments: No trash and debris are present in the channel.

No Photos

Check Point / View

**Airport Way / Down**

Rating **	M	Issue No.	<b>86</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c _ 2012_86			

Action/Comments

Inspector Comments: Minimal vegetation and logs may impede the flow of the channel.

Photo 1 of 1 : CH\_2015\_NA0017\_42\_86\_20150819\_00065.jpg



View of the channel looking downstream.

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
Airport Way / Down (cont)				
Rating **	A	Issue No.	87	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c _ 2012_87			
Action/Comments				
Inspector Comments: No shoaling was found during the inspection.				

No Photos

No Photos

Rating **	A	Issue No.	88	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c _ 2012_88			
Action/Comments				
Inspector Comments: No erosion is present at this location.				

No Photos

No Photos

Rating **	N	Issue No.	89	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c _ 2012_89			
Action/Comments				
Inspector Comments: No revetments are present at this location.				

No Photos

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
Airport Way / Down (cont)				
Rating **	A	Issue No.	90	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c _ 2012_90			
Action/Comments				
Inspector Comments: No trash or debris was present during the inspection.				

No Photos

Check Point / View				
Producers Drive / Up				
Rating **	A	Issue No.	91	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433
Category	Rivers, Channels & Designated Flood			-121.269214
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c _ 2012_91			
Action/Comments				
Inspector Comments: Minimal vegetation may not impede the flow of the channel.				

Photo 1 of 1 : CH\_2015\_NA0017\_42\_91\_20150819\_00066.jpg



View of the channel looking upstream.

Rating **	A	Issue No.	92	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c _ 2012_92			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
Producers Drive / Up (cont)				
Rating **	A	Issue No.	93	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c _ 2012_93			
Action/Comments				
Inspector Comments: No erosion is present at this location.				

No Photos

Rating **	N	Issue No.	94	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c _ 2012_94			
Action/Comments				
Inspector Comments: No revetments are present at this location.				

No Photos

Rating **	A	Issue No.	95	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c _ 2012_95			
Action/Comments				
Inspector Comments: No trash was found during the inspection.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Producers Drive / Down**

Rating **	A	Issue No.	96	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c _ 2012_96			
Action/Comments				
Inspector Comments: The flow is not impeded.				

Photo 1 of 1 : CH\_2015\_NA0017\_42\_96\_20150819\_00067.jpg



View of the channel looking downstream.

Rating **	A	Issue No.	97	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c _ 2012_97			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

Rating **	A	Issue No.	98	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c _ 2012_98			
Action/Comments				
Inspector Comments: No erosion is present at this location.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
Producers Drive / Down (cont)				
Rating **	N	Issue No.	99	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c _ 2012_99			
Action/Comments				
Inspector Comments: No revetments are present at this location.				

No Photos

No Photos

Rating **	A	Issue No.	100	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c _ 2012_100			
Action/Comments				
Inspector Comments: No trash or debris is present in the channel.				

No Photos

No Photos

Check Point / View				
McKinley Avenue / Up				
Rating **	U	Issue No.	101	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c _ 2012_101			
Action/Comments				
Inspector Comments: Vegetation, logs and other debris could impede the flow of the channel.				

Photo 1 of 1 : CH\_2015\_NA0017\_42\_101\_20150819\_00068.jpg

A photograph showing a bridge crossing a channel. The foreground is filled with dense, tall grass and weeds, some of which are brown and dry. A gravel path or clearing is visible on the left. In the background, there are utility poles, trees, and some buildings under a clear blue sky. The date '07/16/2015' is printed in orange in the bottom right corner of the photo.

Photo 1 of 1 : CH\_2015\_NA0017\_42\_101\_20150819\_00068.jpg



View of the heavy vegetation on the channel looking upstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**McKinley Avenue / Up (cont)**

Rating **	M	Issue No.	102	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c _ 2012_102			
Action/Comments				
Inspector Comments: Non aquatic grasses and sedimentation were present during the inspection.				

No Photos

Rating **	A	Issue No.	103	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c _ 2012_103			
Action/Comments				
Inspector Comments: No erosion is present at this location.				

No Photos

Rating **	N	Issue No.	104	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c _ 2012_104			
Action/Comments				
Inspector Comments: No revetments are present at this location.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**McKinley Avenue / Up (cont)**

Rating **	M	Issue No.	105	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c _ 2012_105			

Action/Comments

Inspector Comments: Trash and debris are present on the channel.

No Photos

Check Point / View

**McKinley Avenue / Down**

Rating **	M	Issue No.	106	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c _ 2012_106			

Action/Comments

Inspector Comments: Vegetation and debris may impede the flow of the channel.

Photo 1 of 1 : CH\_2015\_NA0017\_42\_106\_20150819\_00069.jpg



View of the vegetation looking downstream of the channel.

Rating **	A	Issue No.	107	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c _ 2012_107			

Action/Comments

Inspector Comments: No sedimentation is present at this location.

No Photos

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
McKinley Avenue / Down (cont)				
Rating **	A	Issue No.	108	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c _ 2012_108			
Action/Comments				
Inspector Comments: No erosion is present at this location.				

No Photos

Rating **	N	Issue No.	109	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c _ 2012_109			
Action/Comments				
Inspector Comments: No revetments are present at this location.				

No Photos

Rating **	A	Issue No.	110	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c _ 2012_110			
Action/Comments				
Inspector Comments: No trash and debris are present on the channel.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



**Flood Control Project Maintenance****Unit Cover Sheet****2015 Channel Inspection Results****San Joaquin County Flood Control and Water Conservation District**

Channel
South Littlejohn Creek

Channel Rating	<b>M</b>
Date of Inspection	07/13/2015 - 07/17/2015
DWR Inspector	Pavel Kazi
Accompanied By	Jay Jauregui SJCFC&WCD

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Farmington Dam / Up**

Rating **	A	Issue No.	119	GPS Lat/Long
Issue Type +	Ma	Location *		37.900580 °
Category	Rivers, Channels & Designated Flood			-120.936018 °
Item	Gates			
DWR ID	DWR_NA0017_44_c_2014_119			
Action/Comments				
Inspector Comments: The gate appears to be functional.				

Photo 1 of 1 : CH\_2015\_NA0017\_44\_119\_20150817\_00051.jpg



View of the release gate from Farmington Dam looking upstream of the creek.

Check Point / View

**Farmington Dam / Down**

Rating **	A	Issue No.	6	GPS Lat/Long
Issue Type +	Ma	Location *		37.900875 °
Category	Rivers, Channels & Designated Flood			-120.934847 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_6			
Action/Comments				
Inspector Comments: Minimal vegetation was present on the channel. The flow is not impeded.				

Photo 1 of 1 : CH\_2015\_NA0017\_44\_6\_20150817\_00052.jpg



View of the vegetation on the channel looking downstream.

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
Farmington Dam / Down (cont)				
Rating **	A	Issue No.	7	GPS Lat/Long
Issue Type +	Ma	Location *		37.900914 °
Category	Rivers, Channels & Designated Flood			-120.934604 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c _ 2012_7			
Action/Comments				
Inspector Comments: No sedimentation is present in the channel.				

No Photos

Rating **	U	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		37.900914
Category	Rivers, Channels & Designated Flood			-120.934604
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c _ 2012_8			
Action/Comments				
Inspector Comments: Erosion got worse since last year.				

Photo 1 of 3 : CH\_2015\_NA0017\_44\_8\_20150817\_00053.jpg



View of the erosion on the left of the channel looking downstream during 2015 inspection.

Rating **	U	Issue No.	8 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.900914 °
Category	Rivers, Channels & Designated Flood			-120.934604 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c _ 2012_8			

Photo 2 of 3 : CH\_2015\_NA0017\_44\_8\_20150710\_00003.jpg



Erosion was found on the channel bank looking downstream during 2014 inspection.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Farmington Dam / Down (cont)**

Rating **	U	Issue No.	8 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.900914 °
Category	Rivers, Channels & Designated Flood			-120.934604 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_8			
Action/Comments				
Inspector Comments: Erosion got worse since last year.				

Photo 3 of 3 : CH\_2015\_NA0017\_44\_8\_20150710\_00004.jpg



Erosion was found on the channel banks looking downstream during 2013 inspection.

Rating **	A	Issue No.	9	GPS Lat/Long
Issue Type +	Ma	Location *		37.900914 °
Category	Rivers, Channels & Designated Flood			-120.934604 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_9			
Action/Comments				
Inspector Comments: Existing riprap appeared to be maintained.				

Photo 1 of 2 : CH\_2015\_NA0017\_44\_9\_20150817\_00054.jpg



View of the existing revetments looking downstream during 2015 inspection.

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
Farmington Dam / Down (cont)				
Rating **	A	Issue No.	9 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.900914
Category	Rivers, Channels & Designated Flood			-120.934604
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_9			
Action/Comments				
Inspector Comments: Existing riprap appeared to be maintained.				

Photo 2 of 2 : CH\_2015\_NA0017\_44\_9\_20150710\_00005.jpg



Existing revetments were covered by soil and appeared to be holding in place. The picture was taken looking upstream of the channel during 2014 inspection.

Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		37.900914
Category	Rivers, Channels & Designated Flood			-120.934604
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_10			
Action/Comments				
Inspector Comments: No debris are present in the channel.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Wedding Chappel Crossing / Up**

Rating **	A	Issue No.	<b>99</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.900307 °
Category	Rivers, Channels & Designated Flood			-120.938492 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c _ 2013_99			

Action/Comments

Inspector Comments: Minimal vegetation may not impede the flow of the channel.

Photo 1 of 1 : CH\_2015\_NA0017\_44\_99\_20150817\_00055.jpg



View of the vegetation on the channel looking upstream.

Rating **	A	Issue No.	<b>100</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.900040 °
Category	Rivers, Channels & Designated Flood			-120.938949 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c _ 2013_100			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

Rating **	A	Issue No.	<b>101</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.900040 °
Category	Rivers, Channels & Designated Flood			-120.938949 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c _ 2013_101			

Action/Comments

Inspector Comments: No erosion was found during the inspection.

No Photos

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
Wedding Chappel Crossing / Up (cont)				
Rating **	N	Issue No.	112	GPS Lat/Long
Issue Type +	Ma	Location *		37.900040 °
Category	Rivers, Channels & Designated Flood			-120.938949 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2013_112			
Action/Comments				
Inspector Comments: No revetments exist at this location.				

No Photos

Rating **	A	Issue No.	103	GPS Lat/Long
Issue Type +	Ma	Location *		37.900040 °
Category	Rivers, Channels & Designated Flood			-120.938949 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2013_103			
Action/Comments				
Inspector Comments: No debris was found during inspection.				

No Photos

Rating **	M	Issue No.	108	GPS Lat/Long
Issue Type +	Ma	Location *		37.900040 °
Category	Rivers, Channels & Designated Flood			-120.938949 °
Item	Gates			
DWR ID	DWR_NA0017_44_c_2013_108			
Action/Comments				
Inspector Comments: The pipe appeared to be in good condition, but accumulated debris may block the flow inside the pipe.				

Photo 1 of 2 : CH\_2015\_NA0017\_44\_108\_20150818\_00056.jpg



View of the pipe looking upstream of the channel during 2015 inspection.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Wedding Chappel Crossing / Up (cont)**

Rating **	M	Issue No.	<b>108 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.900040 °
Category	Rivers, Channels & Designated Flood			-120.938949 °
Item	Gates			
DWR ID	DWR_NA0017_44_c_2013_108			

Action/Comments

Inspector Comments: The pipe appeared to be in good condition, but accumulated debris may block the flow inside the pipe.

Photo 2 of 2 : CH\_2015\_NA0017\_44\_108\_20150710\_00046.jpg



View of the gate looking upstream of the channel during 2014 inspection.

Check Point / View

**Wedding Chappel Crossing / Down**

Rating **	U	Issue No.	<b>104</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.900332 °
Category	Rivers, Channels & Designated Flood			-120.939298 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2013_104			

Action/Comments

Inspector Comments: Heavy vegetation growth will impede the flow and may block approximately 50% capacity of the channel.

Photo 1 of 2 : CH\_2015\_NA0017\_44\_104\_20150818\_00057.jpg



View of the vegetation on the downstream of the channel during 2015 inspection.

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable                      N : Not Inspected/Rated  
M : Minimally Acceptable        C : Corrected  
U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Wedding Chappel Crossing / Down (cont)**

Rating **	U	Issue No.	<b>104 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.900332 °
Category	Rivers, Channels & Designated Flood			-120.939298 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2013_104			

Action/Comments

Inspector Comments: Heavy vegetation growth will impede the flow and may block approximately 50% capacity of the channel.

Photo 2 of 2 : CH\_2015\_NA0017\_44\_104\_20150710\_00042.jpg



Heavy vegetation was present on the downstream of the channel during 2014 inspection.

Rating **	A	Issue No.	<b>105</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.900040 °
Category	Rivers, Channels & Designated Flood			-120.938949 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2013_105			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

Rating **	A	Issue No.	<b>106</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.900040 °
Category	Rivers, Channels & Designated Flood			-120.938949 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2013_106			

Action/Comments

Inspector Comments: No erosion was found during the inspection.

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Wedding Chappel Crossing / Down (cont)**

Rating **	U	Issue No.	107	GPS Lat/Long
Issue Type +	Ma	Location *		37.900040 °
Category	Rivers, Channels & Designated Flood			-120.938949 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2013_107			

Action/Comments

Inspector Comments: Various debris and tree trunks were present on the channel during the inspection.

Photo 1 of 1 : CH\_2015\_NA0017\_44\_107\_20150820\_00091.jpg



View of obstructions on the channel looking upstream.

Check Point / View

**Henry Road / Up**

Rating **	A	Issue No.	141	GPS Lat/Long
Issue Type +	Ma	Location *		37.903161 °
Category	Rivers, Channels & Designated Flood			-120.945289 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2015_141			

Action/Comments

Inspector Comments: Minimal vegetation was present, but the flow is not impeded.

Photo 1 of 1 : CH\_2015\_NA0017\_44\_141\_20150818\_00058.jpg



View of vegetation on the upstream of the channel.

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
Henry Road / Up (cont)				
Rating **	A	Issue No.	142	GPS Lat/Long
Issue Type +	Ma	Location *		37.903161 °
Category	Rivers, Channels & Designated Flood			-120.945289 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c _ 2015_142			
Action/Comments				
Inspector Comments: No sedimentation was present.				

No Photos

No Photos

Rating **	A	Issue No.	143	GPS Lat/Long
Issue Type +	Ma	Location *		37.903161 °
Category	Rivers, Channels & Designated Flood			-120.945289 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c _ 2015_143			
Action/Comments				
Inspector Comments: No erosion was found.				

No Photos

No Photos

Rating **	A	Issue No.	144	GPS Lat/Long
Issue Type +	Ma	Location *		37.903161 °
Category	Rivers, Channels & Designated Flood			-120.945289 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c _ 2015_144			
Action/Comments				
Inspector Comments: No debris was found that could obstruct the flow of the channel.				

No Photos

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Henry Road / Up (cont)**

Rating **	A	Issue No.	150	GPS Lat/Long
Issue Type +	Ma	Location *		37.903161 °
Category	Rivers, Channels & Designated Flood			-120.945289 °
Item	Gates			
DWR ID	DWR_NA0017_44_c _ 2015_150			

Action/Comments

Inspector Comments: The pipe appears to be not restricted and it will not impede the flow of the channel.

Photo 1 of 1 : CH\_2015\_NA0017\_44\_150\_20150824\_00092.jpg



View of the pipe looking upstream from the channel.

Check Point / View


**Henry Road / Down**

Rating **	M	Issue No.	146	GPS Lat/Long
Issue Type +	Ma	Location *		37.903161 °
Category	Rivers, Channels & Designated Flood			-120.945289 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c _ 2015_146			

Action/Comments

Inspector Comments: Vegetation growth may impede the flow of the channel.

Photo 1 of 1 : CH\_2015\_NA0017\_44\_146\_20150818\_00060.jpg



View of the vegetation on the downstream of the channel.

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
Henry Road / Down (cont)				
Rating **	A	Issue No.	147	GPS Lat/Long
Issue Type +	Ma	Location *		37.903161 °
Category	Rivers, Channels & Designated Flood			-120.945289 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c _ 2015_147			
Action/Comments				
Inspector Comments: No shoaling or sedimentation was present.				

No Photos

Rating **	A	Issue No.	148	GPS Lat/Long
Issue Type +	Ma	Location *		37.903161 °
Category	Rivers, Channels & Designated Flood			-120.945289 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c _ 2015_148			
Action/Comments				
Inspector Comments: No erosion was present during inspection.				

No Photos

Rating **	A	Issue No.	149	GPS Lat/Long
Issue Type +	Ma	Location *		37.903161 °
Category	Rivers, Channels & Designated Flood			-120.945289 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c _ 2015_149			
Action/Comments				
Inspector Comments: No trash was present.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Escalon Bellota Rd / Up**

Rating **	A	Issue No.	21	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_21			

Action/Comments

Inspector Comments: No vegetation was impeding the flow of the channel.

Photo 1 of 2 : CH\_2015\_NA0017\_44\_21\_20150818\_00061.jpg



View of the channel looking upstream during 2015 inspection.

Photo 2 of 2 : CH\_2015\_NA0017\_44\_21\_20150710\_00007.jpg



Tree branches may cause obstruction on the channel. The picture was taken looking upstream during 2014 inspection.

Rating **	A	Issue No.	22	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_22			

Action/Comments

Inspector Comments: No sedimentation is present in the channel.

No Photos

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
Escalon Bellota Rd / Up (cont)				
Rating **	A	Issue No.	23	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c _ 2012_23			
Action/Comments				
Inspector Comments: No erosion or bank caving is present.				

No Photos

Rating **	A	Issue No.	24	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330
Category	Rivers, Channels & Designated Flood			-121.000120
Item	Revetments			
DWR ID	DWR_NA0017_44_c _ 2012_24			
Action/Comments				
Inspector Comments: Existing riprap is properly maintained.				

Photo 1 of 2 : CH\_2015\_NA0017\_44\_24\_20150818\_00062.jpg



View of the revetments looking upstream during 2015 inspection.

Rating **	A	Issue No.	<b>24 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c _ 2012_24			

Photo 2 of 2 : CH\_2015\_NA0017\_44\_24\_20150710\_00009.jpg



Existing revetments are properly maintained looking upstream of the channel.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
Escalon Bellota Rd / Up (cont)				
Rating **	A	Issue No.	25	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c _ 2012_25			
Action/Comments				
Inspector Comments: No trash or debris is present on the channel.				

No Photos

Check Point / View				
Escalon Bellota Rd / Down				
Rating **	A	Issue No.	26	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c _ 2012_26			
Action/Comments				
Inspector Comments: No vegetation was found on the channel.				

Photo 1 of 2 : CH\_2015\_NA0017\_44\_26\_20150818\_00063.jpg



View of the channel looking downstream during 2015 inspection.

Photo 2 of 2 : CH\_2015\_NA0017\_44\_26\_20150710\_00010.jpg



View of the channel looking downstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Escalon Bellota Rd / Down (cont)**

Rating **	A	Issue No.	27	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c _ 2012_27			
Action/Comments				
Inspector Comments: No sedimentation is present in this channel.				

No Photos

Rating **	A	Issue No.	28	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c _ 2012_28			
Action/Comments				
Inspector Comments: No erosion or bank caving is present.				

No Photos

Rating **	A	Issue No.	29	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c _ 2012_29			
Action/Comments				
Inspector Comments: Existing riprap is properly maintained.				

Photo 1 of 2 : CH\_2015\_NA0017\_44\_29\_20150818\_00064.jpg



View of the revetments on the left of the channel looking downstream.

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
Escalon Bellota Rd / Down (cont)				
Rating **	A	Issue No.	29 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c _ 2012_29			
Action/Comments				
Inspector Comments: Existing riprap is properly maintained.				

Photo 2 of 2 : CH\_2015\_NA0017\_44\_29\_20150710\_00012.jpg



View of the revetments on the right bank of channel looking downstream.

Rating **	A	Issue No.	30	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330
Category	Rivers, Channels & Designated Flood			-121.000120
Item	Encroachments			
DWR ID	DWR_NA0017_44_c _ 2012_30			
Action/Comments				
Inspector Comments: No trash or debris are present in the channel.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Stanley Rd / Up**

Rating **	A	Issue No.	<b>31</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_31			

Action/Comments

Inspector Comments: Minimal vegetation will not impede the flow of the channel.

Rating **	A	Issue No.	<b>31 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_31			

Photo 1 of 2 : CH\_2015\_NA0017\_44\_31\_20150818\_00065.jpg



View of the channel looking upstream during 2015 inspection.

Photo 2 of 2 : CH\_2015\_NA0017\_44\_31\_20150710\_00013.jpg



View of the channel looking upstream during 2014 inspection.

Rating **	A	Issue No.	<b>32</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_32			

Action/Comments

Inspector Comments: No sediment was present in this channel.

No Photos

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
Stanley Rd / Up (cont)				
Rating **	A	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c _ 2012_33			
Action/Comments				
Inspector Comments: No erosion or bank caving is present.				

No Photos

No Photos

Rating **	A	Issue No.	34	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c _ 2012_34			
Action/Comments				
Inspector Comments: Existing revetments were maintained properly on the channel bank.				

Photo 1 of 1 : CH\_2015\_NA0017\_44\_34\_20150818\_00066.jpg



View of the existing revetments on the channel bank looking upstream.

Rating **	A	Issue No.	35	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c _ 2012_35			
Action/Comments				
Inspector Comments: No trash or debris was found during the inspection.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Stanley Rd / Down**

Rating **	M	Issue No.	36	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_36			
Action/Comments				
Inspector Comments: Tree branches might obstruct the downstream flow of the channel.				

Photo 1 of 1 : CH\_2015\_NA0017\_44\_36\_20150818\_00067.jpg



Tree branches might obstruct the flow of the channel looking downstream.

Rating **	A	Issue No.	37	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_37			
Action/Comments				
Inspector Comments: No sediment was present in this channel.				

No Photos

Rating **	A	Issue No.	38	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_38			
Action/Comments				
Inspector Comments: No erosion or bank caving is present at this location.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Stanley Rd / Down (cont)**

Rating **	N	Issue No.	39	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_39			

Action/Comments

Inspector Comments: No revetments are found at this location.

No Photos

Rating **	A	Issue No.	40	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_40			

Action/Comments

Inspector Comments: No trash or debris is present at this location.

No Photos

Check Point / View

**Van Allen Rd / Up**

Rating **	A	Issue No.	41	GPS Lat/Long
Issue Type +	Ma	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_41			

Action/Comments

Inspector Comments: Minimal vegetation growth is present on the channel.

Photo 1 of 1 : CH\_2015\_NA0017\_44\_41\_20150818\_00068.jpg



View of the vegetation on the channel looking upstream.

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Van Allen Rd / Up (cont)**

Rating **	A	Issue No.	<b>42</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_42			

Action/Comments

Inspector Comments: No sediment was present in this channel.

No Photos

Rating **	A	Issue No.	<b>43</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_43			

Action/Comments

Inspector Comments: No erosion or bank caving is present.

No Photos

Rating **	A	Issue No.	<b>44</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_44			

Action/Comments

Inspector Comments: Existing riprap protection is properly maintained.

Photo 1 of 1 : CH\_2015\_NA0017\_44\_44\_20150818\_00069.jpg



View of the revetments on the channel bank looking upstream.

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
Van Allen Rd / Up (cont)				
Rating **	A	Issue No.	45	GPS Lat/Long
Issue Type +	Ma	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c _ 2012_45			
Action/Comments				
Inspector Comments: No trash or debris was found during the inspection.				

No Photos

Check Point / View				
Van Allen Rd / Down				
Rating **	A	Issue No.	46	GPS Lat/Long
Issue Type +	Ma	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c _ 2012_46			
Action/Comments				
Inspector Comments: The vegetation growth around the channel is not impeding the flow.				

Photo 1 of 1 : CH\_2015\_NA0017\_44\_46\_20150818\_00070.jpg



View of the channel looking downstream.

Rating **	A	Issue No.	47	GPS Lat/Long
Issue Type +	Ma	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c _ 2012_47			
Action/Comments				
Inspector Comments: No sediment was present during inspection.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Van Allen Rd / Down (cont)**

Rating **	A	Issue No.	<b>48</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c _ 2012_48			

Action/Comments

Inspector Comments: No erosion or bank caving is present.

No Photos

Rating **	A	Issue No.	<b>49</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c _ 2012_49			

Action/Comments

Inspector Comments: Existing riprap protection is properly maintained.

Photo 1 of 1 : CH\_2015\_NA0017\_44\_49\_20150818\_00071.jpg



View of the existing revetments looking downstream.

Rating **	A	Issue No.	<b>50</b>	GPS Lat/Long
Issue Type +	En	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c _ 2012_50			

Action/Comments

Inspector Comments: No trash or debris is present at this location.

No Photos

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Mariposa Rd / Up**

Rating **	A	Issue No.	51	GPS Lat/Long
Issue Type +	Ma	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c _ 2012_51			

Action/Comments

Inspector Comments: Minimal vegetation is present in the channel.

Photo 1 of 1 : CH\_2015\_NA0017\_44\_51\_20150818\_00072.jpg



View of the vegetation on the upstream of the channel.

Rating **	A	Issue No.	52	GPS Lat/Long
Issue Type +	Ma	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c _ 2012_52			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

Rating **	A	Issue No.	53	GPS Lat/Long
Issue Type +	Ma	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c _ 2012_53			

Action/Comments

Inspector Comments: No erosion or bank caving is present.

No Photos

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
Mariposa Rd / Up (cont)				
Rating **	A	Issue No.	55	GPS Lat/Long
Issue Type +	Ma	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c _ 2012_55			
Action/Comments				
Inspector Comments: No trash or debris is present at this location.				

No Photos

Check Point / View

Mariposa Rd / Down				
Rating **	M	Issue No.	56	GPS Lat/Long
Issue Type +	Ma	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c _ 2012_56			
Action/Comments				
Inspector Comments: Minimal vegetation and some woddy vegetation on the bank may impede the flow of the channel.				

Photo 1 of 1 : CH\_2015\_NA0017\_44\_56\_20150818\_00073.jpg



View of the vegetation on the channel looking downstream.

Rating **	A	Issue No.	57	GPS Lat/Long
Issue Type +	Ma	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c _ 2012_57			
Action/Comments				
Inspector Comments: No sedimentation is present in the channel.				

No Photos

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Mariposa Rd / Down (cont)**

Rating **	A	Issue No.	58	GPS Lat/Long
Issue Type +	Ma	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c _ 2012_58			

Action/Comments

Inspector Comments: No erosion was found during the inspection.

No Photos

Rating **	A	Issue No.	59	GPS Lat/Long
Issue Type +	Ma	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c _ 2012_59			

Action/Comments

Inspector Comments: Existing revetments appears to be undamaged.

Photo 1 of 1 : CH\_2015\_NA0017\_44\_59\_20150818\_00074.jpg



View of existing revetments on the channel banks looking downstream.

Rating **	A	Issue No.	60	GPS Lat/Long
Issue Type +	En	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c _ 2012_60			

Action/Comments

Inspector Comments: No trash or debris was found during the inspection.

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Jack Tone Rd / Up**

Rating **	M	Issue No.	61	GPS Lat/Long
Issue Type +	Ma	Location *		37.880726 °
Category	Rivers, Channels & Designated Flood			-121.146929 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c _ 2012_61			
Action/Comments				
Inspector Comments: Cat tails are obstructing the flow of the channel.				

Photo 1 of 1 : CH\_2015\_NA0017\_44\_61\_20150818\_00075.jpg



View of the vegetation on the upstream of the channel.

Rating **	A	Issue No.	62	GPS Lat/Long
Issue Type +	Ma	Location *		37.880726 °
Category	Rivers, Channels & Designated Flood			-121.146929 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c _ 2012_62			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

Rating **	A	Issue No.	63	GPS Lat/Long
Issue Type +	Ma	Location *		37.880726 °
Category	Rivers, Channels & Designated Flood			-121.146929 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c _ 2012_63			
Action/Comments				
Inspector Comments: No erosion or bank caving is present.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Jack Tone Rd / Up (cont)**

Rating **	A	Issue No.	<b>64</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.880726 °
Category	Rivers, Channels & Designated Flood			-121.146929 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c _ 2012_64			

Action/Comments

Inspector Comments: Existing riprap protection is properly maintained.

Photo 1 of 1 : CH\_2015\_NA0017\_44\_64\_20150818\_00076.jpg



View of existing riprap on the upstream of the channel.

Rating **	A	Issue No.	<b>65</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.880726 °
Category	Rivers, Channels & Designated Flood			-121.146929 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c _ 2012_65			

Action/Comments

Inspector Comments: No trash or debris was found during the inspection.

No Photos

Rating **	M	Issue No.	<b>70</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.880726 °
Category	Rivers, Channels & Designated Flood			-121.146929 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c _ 2012_70			

Photo 2 of 1 : CH\_2015\_NA0017\_44\_70\_20150818\_00079.jpg



View of a pipe with missing flap gate on the upstream of the channel.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Jack Tone Rd / Down**

Rating **	M	Issue No.	66	GPS Lat/Long
Issue Type +	Ma	Location *		37.880726 °
Category	Rivers, Channels & Designated Flood			-121.146929 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c _ 2012_66			
Action/Comments				
Inspector Comments: Vegetation may obstruct the flow of the channel.				

Photo 1 of 1 : CH\_2015\_NA0017\_44\_66\_20150818\_00077.jpg



View of the vegetation in the channel looking downstream.

Rating **	A	Issue No.	67	GPS Lat/Long
Issue Type +	Ma	Location *		37.880726 °
Category	Rivers, Channels & Designated Flood			-121.146929 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c _ 2012_67			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

Rating **	A	Issue No.	68	GPS Lat/Long
Issue Type +	Ma	Location *		37.880726 °
Category	Rivers, Channels & Designated Flood			-121.146929 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c _ 2012_68			
Action/Comments				
Inspector Comments: No erosion is present on the channel bank.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Jack Tone Rd / Down (cont)**

Rating **	A	Issue No.	69	GPS Lat/Long
Issue Type +	Ma	Location *		37.880726 °
Category	Rivers, Channels & Designated Flood			-121.146929 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c _ 2012_69			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained.				

Photo 1 of 1 : CH\_2015\_NA0017\_44\_69\_20150818\_00078.jpg



View of the existing riprap on the channel bank looking downstream.

Check Point / View

**Austin Rd / Up**

Rating **	A	Issue No.	71	GPS Lat/Long
Issue Type +	Ma	Location *		37.872720 °
Category	Rivers, Channels & Designated Flood			-121.183100 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c _ 2012_71			
Action/Comments				
Inspector Comments: Minimal vegetation is present in the channel, but the flow is not impeded.				

Photo 1 of 1 : CH\_2015\_NA0017\_44\_71\_20150818\_00080.jpg



View of vegetation in the upstream the channel.

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
Austin Rd / Up (cont)				
Rating **	A	Issue No.	72	GPS Lat/Long
Issue Type +	Ma	Location *		37.872720 °
Category	Rivers, Channels & Designated Flood			-121.183100 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c _ 2012_72			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

No Photos

Rating **	A	Issue No.	73	GPS Lat/Long
Issue Type +	Ma	Location *		37.872720 °
Category	Rivers, Channels & Designated Flood			-121.183100 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c _ 2012_73			
Action/Comments				
Inspector Comments: No erosion or bank caving is present.				

No Photos

No Photos

Rating **	N	Issue No.	74	GPS Lat/Long
Issue Type +	Ma	Location *		37.872720 °
Category	Rivers, Channels & Designated Flood			-121.183100 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c _ 2012_74			
Action/Comments				
Inspector Comments: No revetments are present at this location.				

No Photos

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
Austin Rd / Up (cont)				
Rating **	A	Issue No.	75	GPS Lat/Long
Issue Type +	En	Location *		37.872720 °
Category	Rivers, Channels & Designated Flood			-121.183100 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c _ 2012_75			
Action/Comments				
Inspector Comments: No trash or debris was found during the inspection.				

No Photos

No Photos

Check Point / View				
Austin Rd / Down				
Rating **	A	Issue No.	76	GPS Lat/Long
Issue Type +	Ma	Location *		37.872720 °
Category	Rivers, Channels & Designated Flood			-121.183100 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c _ 2012_76			
Action/Comments				
Inspector Comments: Minimal vegetation growth is found, but it doesn't appear to impede the flow of the channel.				

Photo 1 of 1 : CH\_2015\_NA0017\_44\_76\_20150818\_00081.jpg




Photo 1 of 1 : CH\_2015\_NA0017\_44\_76\_20150818\_00081.jpg



View of the vegetation on the downstream end of the channel.

Rating **	A	Issue No.	77	GPS Lat/Long
Issue Type +	Ma	Location *		37.872720 °
Category	Rivers, Channels & Designated Flood			-121.183100 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c _ 2012_77			
Action/Comments				
Inspector Comments: No sediment was present during inspection.				

No Photos

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
Austin Rd / Down (cont)				
Rating **	A	Issue No.	78	GPS Lat/Long
Issue Type +	Ma	Location *		37.872720 °
Category	Rivers, Channels & Designated Flood			-121.183100 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c _ 2012_78			
Action/Comments				
Inspector Comments: No erosion or bank caving is present.				

No Photos

No Photos

Rating **	A	Issue No.	79	GPS Lat/Long
Issue Type +	Ma	Location *		37.872720 °
Category	Rivers, Channels & Designated Flood			-121.183100 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c _ 2012_79			
Action/Comments				
Inspector Comments: Existing revetments are properly maintained.				

Photo 1 of 1 : CH\_2015\_NA0017\_44\_79\_20150818\_00082.jpg

A photograph showing a roadside revetment structure. The structure consists of a concrete wall with a layer of grey rocks on top, separating a paved road from a grassy embankment. The date stamp '07/14/2015' is visible in the bottom right corner of the photo.

Photo 1 of 1 : CH\_2015\_NA0017\_44\_79\_20150818\_00082.jpg



View of the revetments on the downstream of the channel.

Rating **	A	Issue No.	80	GPS Lat/Long
Issue Type +	Ma	Location *		37.872720 °
Category	Rivers, Channels & Designated Flood			-121.183100 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c _ 2012_80			
Action/Comments				
Inspector Comments: Debris was found,but it may not impede the flow of the channel.				

No Photos

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Highway 99 / Up**

Rating **	M	Issue No.	81	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c _ 2012_81			
Action/Comments				
Inspector Comments: Vegetation growth may impede the flow of the channel.				

Photo 1 of 1 : CH\_2015\_NA0017\_44\_81\_20150818\_00083.jpg



View of vegetation on the upstream end of the channel.

Rating **	M	Issue No.	82	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c _ 2012_82			
Action/Comments				
Inspector Comments: Non aquatic grasses are present at this location.				

No Photos

Rating **	M	Issue No.	83	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c _ 2012_83			
Action/Comments				
Inspector Comments: Erosion is present on the bank of the channel.				

Photo 1 of 1 : CH\_2015\_NA0017\_44\_83\_20150818\_00084.jpg



View of the erosion on the channel bank looking upstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Highway 99 / Up (cont)**

Rating **	A	Issue No.	84	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c _ 2012_84			

Action/Comments

Inspector Comments: Existing revetments were properly maintained at this location.

Photo 1 of 1 : CH\_2015\_NA0017\_44\_84\_20150818\_00085.jpg



View of the existing revetments on the upstream end of the channel.

Rating **	A	Issue No.	85	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c _ 2012_85			

Action/Comments

Inspector Comments: No trash was present during the inspection.

No Photos

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**Highway 99 / Down**

Rating **	M	Issue No.	86	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c _ 2012_86			
Action/Comments				
Inspector Comments: Minimal vegetation may impede the flow of the channel.				

Photo 1 of 1 : CH\_2015\_NA0017\_44\_86\_20150818\_00088.jpg



View of the vegetation looking downstream of the channel.

Rating **	A	Issue No.	87	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c _ 2012_87			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

Rating **	A	Issue No.	88	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c _ 2012_88			
Action/Comments				
Inspector Comments: No erosion is present.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
Highway 99 / Down (cont)				
Rating **	A	Issue No.	89	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c _ 2012_89			
Action/Comments				
Inspector Comments: Existing riprap was properly maintained at this location.				

Photo 1 of 1 : CH\_2015\_NA0017\_44\_89\_20150818\_00089.jpg



View of the existing revetments on the downstream end of the channel.

Rating **	A	Issue No.	90	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c _ 2012_90			
Action/Comments				
Inspector Comments: No trash was present at this location.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**El Dorado Rd. / Up**

Rating **	A	Issue No.	<b>120</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c _ 2014_120			

Action/Comments

Inspector Comments: Minimal vegetation may not impede the flow of the channel. Tree branches may fall in the channel in future.

Photo 1 of 1 : CH\_2015\_NA0017\_44\_120\_20150818\_00086.jpg



View of the channel looking upstream.

Rating **	A	Issue No.	<b>121</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c _ 2014_121			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

Rating **	A	Issue No.	<b>122</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c _ 2014_122			

Action/Comments

Inspector Comments: No erosion is present.

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View

**El Dorado Rd. / Up (cont)**

Rating **	N	Issue No.	123	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2014_123			

Action/Comments

Inspector Comments: There is no revetment at this location.

No Photos

Rating **	A	Issue No.	124	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2014_124			

Action/Comments

Inspector Comments: No trash or debris was found on the channel.

No Photos

Check Point / View

**El Dorado Rd. / Down**

Rating **	A	Issue No.	125	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2014_125			

Action/Comments

Inspector Comments: Tree branches may fall into the channel, but the flow is not impeded.

Photo 1 of 1 : CH\_2015\_NA0017\_44\_125\_20150818\_00087.jpg



View of the vegetation on the downstream of the channel.

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
El Dorado Rd. / Down (cont)				
Rating **	A	Issue No.	126	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2014_126			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

No Photos

Rating **	A	Issue No.	127	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2014_127			
Action/Comments				
Inspector Comments: No erosion is present.				

No Photos

No Photos

Rating **	N	Issue No.	128	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2014_128			
Action/Comments				
Inspector Comments: There is no revetment at this location.				

No Photos

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/13/2015 07/17/2015	Pavel Kazi

Check Point / View				
El Dorado Rd. / Down (cont)				
Rating **	A	Issue No.	129	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2014_129			
Action/Comments				
Inspector Comments: No trash or debris was found on the channel.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance****Unit Cover Sheet****2015 Channel Inspection Results****San Joaquin County Flood Control and Water Conservation District**

Channel
South Littlejohn Creek North Branch

Channel Rating	<b>A</b>
Date of Inspection	07/14/2015 - 07/16/2015
DWR Inspector	Pavel Kazi
Accompanied By	Jay Jauregui SJCFC&WCD

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/14/2015 07/16/2015	Pavel Kazi

Check Point / View

**Diversion / Down**

Rating **	A	Issue No.	6	GPS Lat/Long
Issue Type +	Ma	Location *		37.888860 °
Category	Rivers, Channels & Designated Flood			-121.130320 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_45_c _ 2012_6			
Action/Comments				
Inspector Comments: Minimal vegetation was present in the channel but it may not impede the flow.				

Photo 1 of 1 : CH\_2015\_NA0017\_45\_6\_20150818\_00016.jpg



View of the confluence looking downstream of the channel.

Rating **	A	Issue No.	7	GPS Lat/Long
Issue Type +	Ma	Location *		37.888860 °
Category	Rivers, Channels & Designated Flood			-121.130320 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_45_c _ 2012_7			
Action/Comments				
Inspector Comments: No sedimentation is present at this location.				

No Photos

Rating **	A	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		37.888860 °
Category	Rivers, Channels & Designated Flood			-121.130320 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_45_c _ 2012_8			
Action/Comments				
Inspector Comments: No erosion or bank caving is present at this location.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/14/2015 07/16/2015	Pavel Kazi

Check Point / View

**Diversion / Down (cont)**

Rating **	N	Issue No.	9	GPS Lat/Long
Issue Type +	Ma	Location *		37.888860 °
Category	Rivers, Channels & Designated Flood			-121.130320 °
Item	Revetments			
DWR ID	DWR_NA0017_45_c _ 2012_9			

Action/Comments

Inspector Comments: No revetments exist at this location.

No Photos

Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		37.888860 °
Category	Rivers, Channels & Designated Flood			-121.130320 °
Item	Encroachments			
DWR ID	DWR_NA0017_45_c _ 2012_10			

Action/Comments

Inspector Comments: No trash was found during inspection.

No Photos

Check Point / View

**Jack Tone Rd / Up**

Rating **	M	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520 °
Category	Rivers, Channels & Designated Flood			-121.146980 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_45_c _ 2012_11			

Action/Comments

Inspector Comments: Vegetation growth was found on the channel may impede the flow of the channel.

Photo 1 of 1 : CH\_2015\_NA0017\_45\_11\_20150818\_00017.jpg



View of the vegetation upstream end of the channel.

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/14/2015 07/16/2015	Pavel Kazi

Check Point / View				
Jack Tone Rd / Up (cont)				
Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520 °
Category	Rivers, Channels & Designated Flood			-121.146980 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_45_c _ 2012_12			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

No Photos

Rating **	A	Issue No.	13	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520 °
Category	Rivers, Channels & Designated Flood			-121.146980 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_45_c _ 2012_13			
Action/Comments				
Inspector Comments: No erosion or bank caving is present at this location.				

No Photos

No Photos

Rating **	A	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520 °
Category	Rivers, Channels & Designated Flood			-121.146980 °
Item	Revetments			
DWR ID	DWR_NA0017_45_c _ 2012_14			
Action/Comments				
Inspector Comments: Existing riprap is properly maintained in this site.				

Photo 1 of 1 : CH\_2015\_NA0017\_45\_14\_20150818\_00018.jpg




Photo 1 of 1 : CH\_2015\_NA0017\_45\_14\_20150818\_00018.jpg



View of the existing riprap on the channel bank looking upstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/14/2015 07/16/2015	Pavel Kazi

Check Point / View				
Jack Tone Rd / Up (cont)				
Rating **	A	Issue No.	15	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520
Category	Rivers, Channels & Designated Flood			-121.146980
Item	Encroachments			
DWR ID	DWR_NA0017_45_c _ 2012_15			
Action/Comments				
Inspector Comments: No trash was found during the inspection.				

No Photos

Check Point / View				
Jack Tone Rd / Down				
Rating **	A	Issue No.	16	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520
Category	Rivers, Channels & Designated Flood			-121.146980
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_45_c _ 2012_16			
Action/Comments				
Inspector Comments: No vegetation was obstructing the flow of the channel.				

Photo 1 of 1 : CH\_2015\_NA0017\_45\_16\_20150818\_00019.jpg



View of the channel looking downstream.

Rating **	A	Issue No.	17	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520
Category	Rivers, Channels & Designated Flood			-121.146980
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_45_c _ 2012_17			
Action/Comments				
Inspector Comments: No sedimentation is present at this location.				

No Photos

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/14/2015 07/16/2015	Pavel Kazi

Check Point / View

**Jack Tone Rd / Down (cont)**

Rating **	M	Issue No.	18	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520 °
Category	Rivers, Channels & Designated Flood			-121.146980 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_45_c _ 2012_18			

Action/Comments

Inspector Comments: Minor erosion or bank caving is present.

Photo 1 of 1 : CH\_2015\_NA0017\_45\_18\_20150818\_00020.jpg



View of bank erosion on the downstream of the channel.

Rating **	A	Issue No.	19	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520 °
Category	Rivers, Channels & Designated Flood			-121.146980 °
Item	Revetments			
DWR ID	DWR_NA0017_45_c _ 2012_19			

Action/Comments

Inspector Comments: Existing revetments appeared to be properly maintained.

Photo 1 of 1 : CH\_2015\_NA0017\_45\_19\_20150818\_00021.jpg



View of the existing revetments on the channel bank looking downstream.

Rating **	A	Issue No.	20	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520 °
Category	Rivers, Channels & Designated Flood			-121.146980 °
Item	Encroachments			
DWR ID	DWR_NA0017_45_c _ 2012_20			

Action/Comments

Inspector Comments: No trash or debris are present at this location.

No Photos

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/14/2015 07/16/2015	Pavel Kazi

Check Point / View

**Austin Rd / Up**

Rating **	A	Issue No.	21	GPS Lat/Long
Issue Type +	Ma	Location *		37.886056
Category	Rivers, Channels & Designated Flood			-121.183664
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_45_c _ 2012_21			
Action/Comments				
Inspector Comments: Minimal vegetation may not obstruct the flow of the channel.				

Photo 1 of 1 : CH\_2015\_NA0017\_45\_21\_20150818\_00022.jpg



View of the vegetation on the upstream of the channel.

Rating **	A	Issue No.	22	GPS Lat/Long
Issue Type +	Ma	Location *		37.886056
Category	Rivers, Channels & Designated Flood			-121.183664
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_45_c _ 2012_22			
Action/Comments				
Inspector Comments: No sedimentation is present at this location.				

No Photos

Rating **	M	Issue No.	23	GPS Lat/Long
Issue Type +	Ma	Location *		37.886056
Category	Rivers, Channels & Designated Flood			-121.183664
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_45_c _ 2012_23			
Action/Comments				
Inspector Comments: Sign of erosion was discovered on the bank of the channel.				

Photo 1 of 1 : CH\_2015\_NA0017\_45\_23\_20150710\_00008.jpg



View of the erosion on the channel bank looking upstream.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/14/2015 07/16/2015	Pavel Kazi

Check Point / View				
Austin Rd / Up (cont)				
Rating **	N	Issue No.	24	GPS Lat/Long
Issue Type +	Ma	Location *		37.886056 °
Category	Rivers, Channels & Designated Flood			-121.183664 °
Item	Revetments			
DWR ID	DWR_NA0017_45_c _ 2012_24			
Action/Comments				
Inspector Comments: No revetments exist at this location.				

No Photos

No Photos

Rating **	A	Issue No.	25	GPS Lat/Long
Issue Type +	Ma	Location *		37.886056 °
Category	Rivers, Channels & Designated Flood			-121.183664 °
Item	Encroachments			
DWR ID	DWR_NA0017_45_c _ 2012_25			
Action/Comments				
Inspector Comments: No trash or debris was found during inspection.				

No Photos

No Photos

<

Photo 1 of 1 : CH\_2015\_NA0017\_45\_26\_20150818\_00023.jpg



View of downstream of the channel.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/14/2015 07/16/2015	Pavel Kazi

Check Point / View				
Austin Rd / Down (cont)				
Rating **	A	Issue No.	27	GPS Lat/Long
Issue Type +	Ma	Location *		37.886056 °
Category	Rivers, Channels & Designated Flood			-121.183664 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_45_c _ 2012_27			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

No Photos

Rating **	A	Issue No.	28	GPS Lat/Long
Issue Type +	Ma	Location *		37.886056 °
Category	Rivers, Channels & Designated Flood			-121.183664 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_45_c _ 2012_28			
Action/Comments				
Inspector Comments: No erosion or bank caving is present at this location.				

No Photos

No Photos

Rating **	N	Issue No.	29	GPS Lat/Long
Issue Type +	Ma	Location *		37.886056 °
Category	Rivers, Channels & Designated Flood			-121.183664 °
Item	Revetments			
DWR ID	DWR_NA0017_45_c _ 2012_29			
Action/Comments				
Inspector Comments: No revetment exists at this location.				

No Photos

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/14/2015 07/16/2015	Pavel Kazi

Check Point / View				
Austin Rd / Down (cont)				
Rating **	A	Issue No.	30	GPS Lat/Long
Issue Type +	En	Location *		37.886056 °
Category	Rivers, Channels & Designated Flood			-121.183664 °
Item	Encroachments			
DWR ID	DWR_NA0017_45_c _ 2012_30			
Action/Comments				
Inspector Comments: No trash or debris was found during inspection.				

No Photos

No Photos

Check Point / View				
Confluence at Airport Way / Up				
Rating **	A	Issue No.	31	GPS Lat/Long
Issue Type +	Ma	Location *		37.876513 °
Category	Rivers, Channels & Designated Flood			-121.236231 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_45_c _ 2012_31			
Action/Comments				
Inspector Comments: Minimal scattered vegetation didn't impede the flow of the channel.				

Photo 1 of 1 : CH\_2015\_NA0017\_45\_31\_20150818\_00028.jpg




Photo 1 of 1 : CH\_2015\_NA0017\_45\_31\_20150818\_00028.jpg



View of the confluence looking upstream.

Rating **	A	Issue No.	32	GPS Lat/Long
Issue Type +	Ma	Location *		37.876513 °
Category	Rivers, Channels & Designated Flood			-121.236231 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_45_c _ 2012_32			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/14/2015 07/16/2015	Pavel Kazi

Check Point / View

**Confluence at Airport Way / Up (cont)**

Rating **	A	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		37.876513 °
Category	Rivers, Channels & Designated Flood			-121.236231 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_45_c _ 2012_33			

Action/Comments

Inspector Comments: No erosion is present at this location.

No Photos

Rating **	N	Issue No.	34	GPS Lat/Long
Issue Type +	Ma	Location *		37.876513 °
Category	Rivers, Channels & Designated Flood			-121.236231 °
Item	Revetments			
DWR ID	DWR_NA0017_45_c _ 2012_34			

Action/Comments

Inspector Comments: No revetments are present at this location.

No Photos

Rating **	A	Issue No.	35	GPS Lat/Long
Issue Type +	Ma	Location *		37.876513 °
Category	Rivers, Channels & Designated Flood			-121.236231 °
Item	Encroachments			
DWR ID	DWR_NA0017_45_c _ 2012_35			

Action/Comments

Inspector Comments: No trash is present.

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/14/2015 07/16/2015	Pavel Kazi

Check Point / View

**Confluence at Airport Way / Down**

Rating **	A	Issue No.	<b>36</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.876513 °
Category	Rivers, Channels & Designated Flood			-121.236231 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_45_c _ 2012_36			

Action/Comments

Inspector Comments: Minimal scattered vegetation didn't impede the flow of the channel.

Photo 1 of 1 : CH\_2015\_NA0017\_45\_36\_20150818\_00027.jpg



View of the downstream of the channel.

Rating **	A	Issue No.	<b>37</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.876513 °
Category	Rivers, Channels & Designated Flood			-121.236231 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_45_c _ 2012_37			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

Rating **	A	Issue No.	<b>38</b>	GPS Lat/Long
Issue Type +	Ma	Location *		37.876513 °
Category	Rivers, Channels & Designated Flood			-121.236231 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_45_c _ 2012_38			

Action/Comments

Inspector Comments: No erosion or bank caving is present at this location

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/14/2015 07/16/2015	Pavel Kazi

Check Point / View

**Confluence at Airport Way / Down (cont)**

Rating **	N	Issue No.	39	GPS Lat/Long
Issue Type +	Ma	Location *		37.876513 °
Category	Rivers, Channels & Designated Flood			-121.236231 °
Item	Revetments			
DWR ID	DWR_NA0017_45_c _ 2012_39			

Action/Comments

Inspector Comments: No revetments exist at this location.

No Photos

Rating **	A	Issue No.	40	GPS Lat/Long
Issue Type +	Ma	Location *		37.876513 °
Category	Rivers, Channels & Designated Flood			-121.236231 °
Item	Encroachments			
DWR ID	DWR_NA0017_45_c _ 2012_40			

Action/Comments

Inspector Comments: No trash or debris is present at this location.

No Photos

Check Point / View

**Highway 99 / Up**

Rating **	M	Issue No.	41	GPS Lat/Long
Issue Type +	Ma	Location *		37.875127 °
Category	Rivers, Channels & Designated Flood			-121.219201 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_45_c _ 2013_41			

Action/Comments

Inspector Comments: Vegetation may impede the flow of the channel.

Photo 1 of 1 : CH\_2015\_NA0017\_45\_41\_20150818\_00024.jpg



View of the vegetation on the upstream end of the channel.

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable                      N : Not Inspected/Rated  
M : Minimally Acceptable        C : Corrected  
U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/14/2015 07/16/2015	Pavel Kazi

Check Point / View				
Highway 99 / Up (cont)				
Rating **	A	Issue No.	42	GPS Lat/Long
Issue Type +	Ma	Location *		37.875127 °
Category	Rivers, Channels & Designated Flood			-121.219201 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_45_c _ 2013_42			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

Rating **	A	Issue No.	43	GPS Lat/Long
Issue Type +	Ma	Location *		37.875127 °
Category	Rivers, Channels & Designated Flood			-121.219201 °
Item	Revetments			
DWR ID	DWR_NA0017_45_c _ 2013_43			
Action/Comments				
Inspector Comments: Existing revetments were properly maintained.				

Photo 1 of 1 : CH\_2015\_NA0017\_45\_43\_20150818\_00025.jpg



View of the existing revetment looking upstream.

Rating **	A	Issue No.	44	GPS Lat/Long
Issue Type +	Ma	Location *		37.875127 °
Category	Rivers, Channels & Designated Flood			-121.219201 °
Item	Encroachments			
DWR ID	DWR_NA0017_45_c _ 2013_44			
Action/Comments				
Inspector Comments: No trash was found at this location.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/14/2015 07/16/2015	Pavel Kazi

Check Point / View

**Highway 99 / Down**

Rating **	A	Issue No.	45	GPS Lat/Long
Issue Type +	Ma	Location *		37.875127
Category	Rivers, Channels & Designated Flood			-121.219201
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_45_c _ 2013_45			
Action/Comments				
Inspector Comments: Vegetation was not imepeding the flow of the channel.				

Photo 1 of 1 : CH\_2015\_NA0017\_45\_45\_20150818\_00029.jpg



View of the channel looking downstream.

Rating **	A	Issue No.	46	GPS Lat/Long
Issue Type +	Ma	Location *		37.875127
Category	Rivers, Channels & Designated Flood			-121.219201
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_45_c _ 2013_46			
Action/Comments				
Inspector Comments: No sedimentation is present at this location.				

No Photos

Rating **	A	Issue No.	47	GPS Lat/Long
Issue Type +	Ma	Location *		37.875127
Category	Rivers, Channels & Designated Flood			-121.219201
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_45_c _ 2013_47			
Action/Comments				
Inspector Comments: No erosion was present during the inspection.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**San Joaquin County Flood Control and Water Conservation District**

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/14/2015 07/16/2015	Pavel Kazi

Check Point / View

**Highway 99 / Down (cont)**

Rating **	A	Issue No.	48	GPS Lat/Long
Issue Type +	Ma	Location *		37.875127 °
Category	Rivers, Channels & Designated Flood			-121.219201 °
Item	Revetments			
DWR ID	DWR_NA0017_45_c _ 2013_48			

Action/Comments

Inspector Comments: Existing revetments were properly maintained.

Photo 1 of 1 : CH\_2015\_NA0017\_45\_48\_20150818\_00030.jpg



View of the revetments on the downstream of the channel.

Rating **	A	Issue No.	49	GPS Lat/Long
Issue Type +	Ma	Location *		37.875127 °
Category	Rivers, Channels & Designated Flood			-121.219201 °
Item	Encroachments			
DWR ID	DWR_NA0017_45_c _ 2013_49			

Action/Comments

Inspector Comments: No trash was present.

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---